



higher education  
& training  
Department:  
Higher Education and Training  
REPUBLIC OF SOUTH AFRICA



**BUFFALO CITY**  
**TVET COLLEGE**

## **REQUEST FOR QUOTATION: REPAIR AND NEW INSTALLATION OF WINDOWS (KSS)**

Kindly see the attached request for quote (RFQ). Quotations should be forwarded to [quotations@bccollege.co.za](mailto:quotations@bccollege.co.za).

**TENDERERS MUST NOTE THAT WHEREVER THIS DOCUMENT REFERS TO ANY PARTICULAR TRADE MARK, NAME, PATENT, DESIGN, TYPE, SPECIFIC ORIGIN OR PRODUCER, SUCH REFERENCE SHALL BE DEEMED TO BE ACCOMPANIED BY THE WORDS 'OR EQUIVALENT.**

Kindly submit the following **REQUIRED** documents when responding to the RFQ

- Signed quotation (quotations not signed will be eliminated)
- Declaration forms (SBD 4, 8 and 9)
- Certified BEE certificate (0 points will be awarded for BEE certificates that are not certified)
- Tax Clearance Certificate
- CSD report
- Bank Confirmation Letter (not older than 3 months)
- Quotations must be detailed as per specification
- **N. B. Compulsory site briefing session will be held at King Street Campus on 19 October 2022 @ 10 am.**

**Closing Date: 26 October 2022 at 12:00 Pm. No late or hand delivered documents will be accepted. ONLY EMAILED DOCUMENTS WILL BE ACCEPTED**

Enquiries: Ms Weziwe Gwabavu / Zimkhitha Jikwana

043 704 9241

---



higher education  
& training

Department:  
Higher Education and Training  
REPUBLIC OF SOUTH AFRICA



**BUFFALO CITY**  
**TVET COLLEGE**

RE: SPECIFICATION FOR REPAIR AND NEW INSTALLATION OF WINDOWS AND BURGLARS AT K'NG STREET SITE.

CIDB GRADING 1GB/HIGHER( PLEASE ATTACH PROOF)

No	Item	Description	Unit	Quantity
<b>FIRST FLOOR KITCHEN</b>				
1	Windows	<ul style="list-style-type: none"> <li>Remove the existing wooden window frame (2100 x 700 mm)</li> <li>Dissemble and remove an existing wooden cabinet.</li> <li>Replace with natural silver aluminium window (2100 x 700 mm) (6.3mm safety glass)</li> <li>Install an obscure glass ( 6.3mm safety glass)</li> <li>Reassemble the wooden cabinet unit.</li> </ul>	Each	1
			Each	1
			Each	1
			Each	1
			Each	1
<b>Venue B11</b>				
2	Windows	<ul style="list-style-type: none"> <li>Remove the existing steel case window (1000 x 650 mm.)</li> <li>Replace with Natural silver aluminium window (1000 x 650 mm). (Note one glass pane to be obscure)</li> </ul>	Each	2
			Each	2
<b>Reception area</b>				
3	Windows	<ul style="list-style-type: none"> <li>Remove the existing wooden frame window (1250 x 1250mm)</li> <li>Replace with natural silver aluminium window (100 x 700mm) (6.3mm safety glass)</li> </ul>	Each	2
			Each	2
	Doors	<ul style="list-style-type: none"> <li>Remove the existing timber door and frame</li> <li>Replace with aluminium standard size door and frame (2040 x 817mm)</li> </ul>	Each	1
			Each	1
	Burglar	<ul style="list-style-type: none"> <li>Remove the existing door burglar guard (2040 x 1030mm)</li> <li>Replace with new retractable burglar guard (2040 x 1030 mm) at the Reception</li> </ul>	Each	1
			Each	1
		<ul style="list-style-type: none"> <li>Remove the existing steel window burglar (1250 x 1250mm)</li> </ul>	Each	2
		<ul style="list-style-type: none"> <li>Replace with aluminium window burglar guards (1250 x 1250mm)</li> </ul>	Each	2
<b>Ground floor Staff Toilet</b>				
4	Windows	<ul style="list-style-type: none"> <li>Remove the existing wooden frame window (950 x 600mm)</li> <li>Replace with natural silver aluminium window (950 x600mm)</li> </ul>	Each	1
			Each	1
<b>Ground floor Student Toilet</b>				
5	Windows	<ul style="list-style-type: none"> <li>Remove the existing wooden window frames (1000 x 700 mm)</li> <li>Replace with natural silver aluminium windows (1000 x 700 mm) (6.3mm Safety glass)</li> </ul>	Each	5
			Each	5
<b>Venue A3</b>				



higher education  
& training

Department:  
Higher Education and Training  
REPUBLIC OF SOUTH AFRICA



**BUFFALO CITY  
WEST COLLEGE**

6	Windows	<ul style="list-style-type: none"> <li>Remove the existing wooden window (1250 x 1250 mm)</li> <li>Replace with natural silver aluminium window (1250 x 1250 mm)(6.3mm Safety glass)</li> <li>Remove the existing double timber door (2030 x 1025mm)</li> <li>Replace with natural silver aluminium double door (2030 x 1025)</li> </ul>	Each	2
			Each	2
	Burglar	<ul style="list-style-type: none"> <li>Remove the existing door burglar guard (2040 x 1030mm)</li> </ul>	Each	1
	Burglar	<ul style="list-style-type: none"> <li>Replace with new retractable burglar guard (2040 x 1030 mm)</li> </ul>	Each	1
	Burglar	<ul style="list-style-type: none"> <li>Remove the existing steel window burglars (1250 x 1250mm)</li> </ul>	Each	2
	Burglar	<ul style="list-style-type: none"> <li>Replace with aluminium window burglar guards (1250 x 1250mm)</li> </ul>	Each	2
<b>Computer Lab</b>				
7	Windows	<ul style="list-style-type: none"> <li>Remove the existing steel case window (1500 x 1300 mm).</li> <li>Replace with natural silver aluminium window (1500 x 1300 mm) (6.3mm Safety glass)</li> </ul>	Each	1
			Each	1
		<ul style="list-style-type: none"> <li>Install aluminium window burglar guard (1500 x 1000)</li> </ul>	Each	1
<b>Simulator Room</b>				
8	Windows	<ul style="list-style-type: none"> <li>Remove the existing wooden frame window (200 x 500mm)</li> </ul>	Each	1
		<ul style="list-style-type: none"> <li>Replace with natural silver aluminium window (200 x 500mm) (6.3mm Safety glass)</li> </ul>	Each	1
<b>Store room</b>				
9	Door	<ul style="list-style-type: none"> <li>Remove the existing timber door (2030 x 810mm)</li> </ul>	Each	1
		<ul style="list-style-type: none"> <li>Replace with new meranti solid timber door size 2030 x 810 mm</li> </ul>	Each	1
<b>Venue A9</b>				
10	Burglar	<ul style="list-style-type: none"> <li>Install retractable burglar door guard (813 x 2032mm)</li> </ul>	Each	1
<b>External Venues</b>				
11	Burglar	<ul style="list-style-type: none"> <li>Install new aluminium window burglar (1500 x 1000mm)</li> </ul>	Each	1
		<ul style="list-style-type: none"> <li>Install new aluminium window burglar (1300 x 1100mm)</li> </ul>	Each	1
	Burglar	<ul style="list-style-type: none"> <li>Install new aluminium door burglar guard (2030 x 810mm)</li> </ul>	Each	1

N.B

1. All patch plaster on all soffits and reveals to be accounted for when quoting including painting with similar paint after work is complete on all affected areas.
2. A compulsory site visit will be conducted. Dates to be on the advert.

  
\_\_\_\_\_  
O. Jwente  
Procurement clerk


04/10/2022  
Date

  
\_\_\_\_\_  
L. Mda  
AD: Occupational programmes

04/10/2022  
Date

  
\_\_\_\_\_  
N Ngxekana  
PM: Infrastructure Construction and Maintenance

04/10/2022  
Date

  
\_\_\_\_\_  
B. Timothy  
Manager: SCM

13/10/2022  
Date

NB: Note revised BOQ and Briefing required.